


Unsafe

Sobhuza St, Silobela, Carolina, 1185, South Africa



Test Conditions

Loaded Date	22-09-2023 09:51	Test Date	22-09-2023
Water Source	Tap water	Testing Method	watercan
Province	Mpumalanga	Municipality	Gert Sibande District Municipality

Environmental Parameters

Water Colour	Yellow
Smell Present	No

Chemical Analysis

Test	Value	Quality
Nitrate	0.5	Safe
Nitrite	0	Safe
Phosphate	50	Unsafe
Hardness	50	-
Total Chlorine	10	Warning
Free Chlorine	0	Safe
Bromine	0	Safe
Alkalinity	0	-
pH	7.2	Safe
Metals	-	Safe

Bacterial Analysis

Test	Value	Quality
Waited 36 Hours	true	
Coliform Colour	Black	Unsafe
First Results (Hours)	72	
Plate Clear	false	Unsafe
Blue Spots	11	
Red Spots	11	